Page -1

DAILY REPORT

			<u>DF</u>	ILY REPORT				Page -1
						Reporting Date :	9-Dec-08	
Till now the max	timum generatio	n is : -	4130.0 MW at	20:00	on	17-Sep-07		
The Summary of Yesterday's (8-Dec-08) Generation & Demand		Todav's Actual Mir	n Gen. & Probable	Gen. & Demand		
Day Peak Genera		2277.0	MW Hour :	9:00	Min Gen. at	4:00		99 MW
Evening Peak Ger		3607.3	MW Hour :	18:30	Max Generation			30 MW
E.P. Demand (at o		3607.3	MW Hour :	18:30	Max Demand	:		00 MW
Maximum Genera		3607.3	MW Hour :	18:30	Shortage	:	33	0 MW
		59.29		68.48%	Load Shed			MW
Total Gen. (MKWI	п) .		System L/ Factor :		Load Sned	· · · · · · · · · · · · · · · · · · ·		10100
01			ORT/IMPORT THROUGH EAST-WEST			_		
Export from Ghora					18:30	Energy		00 KWHR.
Import from Ishuro	di to Ghorasal:-		-	MW at	-	Energy	-	KWHR.
		Water Level of Kapta	i Lake at 6:00 A M of	9-Dec-08				
Actual :	83.75	Ft.(MSL),		Rule curve: 105.37	Ft.(MSL)			
Gas Consumed:	Total	535.74	MMCFt.	Oil Consume	d (PDB):	SKO :	0	Liter
						HSD :	217916	Liter
						FO :	476367	Liter
Cost of the Consu	med Fuel (PDR)	· Gas ·	Tk39,596,780	Oil :	Tk11,231,85	59 Total :	Tk50,828,6	30
Cost of the Corisu	illed i dei (i DD)			Oli .	1811,231,00	oo iolai .	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	33
		Load Shedding & O	ther Information					
A		le			T			
Area	Yesterd				Today		T-E	
		edding (s/s end), MW	Estimated Demand(s/s	end)	Estimated Shedd		Rates of Shedo	
	from -	to -	MW			MW	(On Estimated D	Demand)
Dhaka	-	· 	1564			-		-
Chittagong Area	-		465			-		-
Khulna Area	-		415			-		-
Rajshahi Area	-		331			-		-
Comilla Area	_		254		İ	_		_
Mymensing Area	_		192			_		_
Sylhet Area			153					
-	-		77			-		-
Barisal Area	-					-		-
Rangpur Area	-		162		İ	-	İ	-
		,						
Total	0	() 3613		!	0		
	1.6							
	informatio	on of the Generating ma	chines under maintenance					
			:	Forced S	hut- Down			
Pla	nned Shut- Dow	n	3					
	nned Shut- Dow	<u>n</u>	1) Kantai- 3 (19/04/08)					
Pla 1) Khulna 60 MW (05/		n	1) Kaptai- 3 (19/04/08)	9) Sikalbaha Ba	arge (19/06/08)			
		n	2) Raozan -1 (19/11/08)	9) Sikalbaha Ba 10) Sikalbaha S	arge (19/06/08) steam (21/11/08)			
		n	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08)	9) Sikalbaha Ba	arge (19/06/08) steam (21/11/08)			
		n	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08)	9) Sikalbaha Ba 10) Sikalbaha S	arge (19/06/08) steam (21/11/08)			
		n	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08)	9) Sikalbaha Ba 10) Sikalbaha S	arge (19/06/08) steam (21/11/08)			
		n	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08)	9) Sikalbaha Ba 10) Sikalbaha S	arge (19/06/08) steam (21/11/08)			
		n	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08)	9) Sikalbaha Ba 10) Sikalbaha S	arge (19/06/08) steam (21/11/08)			
		n	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08)	9) Sikalbaha Ba 10) Sikalbaha S	arge (19/06/08) steam (21/11/08)			
	07/06)		2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08)	9) Sikalbaha Be 10) Sikalbaha S 11) Shahjibazar	arge (19/06/08) steam (21/11/08)			
	07/06)		2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08)	9) Sikalbaha Be 10) Sikalbaha S 11) Shahjibazar	arge (19/06/08) steam (21/11/08)			
	07/06) Additional Info	ormation of Machines,	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) lines, Interruption / Forced Load sh	9) Sikalbaha Be 10) Sikalbaha S 11) Shahjibazar ed etc.	irge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
1) Khuina 60 MW (05/	Additional Info	ormation of Machines,	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) lines, Interruption / Forced Load sh	9) Sikalbaha Ba 10) Sikalbaha S 11) Shahjibazar ed etc.	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
1) Khuina 60 MW (05/	Additional Info	ormation of Machines,	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) lines, Interruption / Forced Load sh	9) Sikalbaha Be 10) Sikalbaha S 11) Shahjibazar ed etc.	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
1) Khuina 60 MW (05/	Additional Info	ormation of Machines,	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) lines, Interruption / Forced Load sh	9) Sikalbaha Ba 10) Sikalbaha S 11) Shahjibazar ed etc.	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
a) There was no ge	Additional Info	ormation of Machines, e in the evening peak ho	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) lines, Interruption / Forced Load shary yesterday.	ed etc. Forced load So no load Sh	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
a) There was no ge	Additional Info	ormation of Machines, e in the evening peak ho	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) lines, Interruption / Forced Load sh	ed etc. Forced load So no load Sh	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
a) There was no ge	Additional Info	ormation of Machines, e in the evening peak ho	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) lines, Interruption / Forced Load shary yesterday.	ed etc. Forced load So no load Sh	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
a) There was no ge b) Due to gas limits 5 & 6 are under	Additional Info Description Peneration shortage ation, Sikalbaha E	ormation of Machines, e in the evening peak hou Barge & St, Raozan -1, H	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) lines, Interruption / Forced Load sharipur SBU GT-2 and Shahjibazar -2, 4	ed etc. Forced load So no load Sh	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
a) There was no ge b) Due to gas limita 5 & 6 are under c) Ashuganj Stean	Additional Info Description Peneration shortage ation, Sikalbaha Estatut down. In unit -2 was shu	e in the evening peak hour arge & St. Raozan -1, Hout down at 23:15 due to	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) 8) Ilines, Interruption / Forced Load sharipur SBU GT-2 and Shahjibazar -2, 4 steam pipe line leakage.	ed etc. Forced load So no load Sh	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
a) There was no ge b) Due to gas limita 5 & 6 are under c) Ashuganj Stean d) Fenchuganj CC	Additional Info Description eneration shortage ation, Sikalbaha E shut down. m unit -2 was shu EPP GT-1 tripped	e in the evening peak hour argue & St, Raozan -1, Hout down at 23:15 due to did at 02:45 (09/12/08) du	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) 8 Innes, Interruption / Forced Load sharipur SBU GT-2 and Shahjibazar -2, 4 steam pipe line leakage. e to bypass damper problem.	9) Sikalbaha Be 10) Sikalbaha S 11) Shahjibazar ed etc. Forced load So no load she	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
a) There was no ge b) Due to gas limits 5 & 6 are under c) Ashuganj Stean d) Fenchuganj CC e) Meghnaghat Pc	Additional Info Description eneration shortage ation, Sikalbaha E shut down. m unit -2 was shu EPP GT-1 tripped	e in the evening peak hour argue & St, Raozan -1, Hout down at 23:15 due to did at 02:45 (09/12/08) du	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) 8) Ilines, Interruption / Forced Load sharipur SBU GT-2 and Shahjibazar -2, 4 steam pipe line leakage.	9) Sikalbaha Be 10) Sikalbaha S 11) Shahjibazar ed etc. Forced load So no load she	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
a) There was no ge b) Due to gas limita 5 & 6 are under c) Ashuganj CC e) Meghnaghat Porespectively	Additional Info Description Eneration shortage ation, Sikalbaha E shut down. n unit -2 was shu EPP GT-1 tripped ower Ltd. GT-2 a	e in the evening peak hot Barge & St, Raozan -1, H at down at 23 :15 due to d at 02:45 (09/12/08) du nd Steam units were sc	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) lines, Interruption / Forced Load sharipur SBU GT-2 and Shahjibazar -2, 4 steam pipe line leakage. e to bypass damper problem. heduled shut down at 07:43 (09/12/08)	ed etc. Forced load So no load she	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
a) There was no ge b) Due to gas limita 5 & 6 are under c) Ashuganj Stean d) Fenchuganj CC e) Meghnaghat Porespectively. f) Ghorasal 132/33	Additional Info Description Eneration shortage ation, Sikalbaha E shut down. n unit -2 was shu EPP GT-1 tripped ower Ltd. GT-2 a	e in the evening peak hot Barge & St, Raozan -1, H at down at 23 :15 due to d at 02:45 (09/12/08) du nd Steam units were sc	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) 8 Innes, Interruption / Forced Load sharipur SBU GT-2 and Shahjibazar -2, 4 steam pipe line leakage. e to bypass damper problem.	ed etc. Forced load So no load she	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
a) There was no ge b) Due to gas limita 5 & 6 are under c) Ashuganj Stean d) Fenchuganj CC e) Meghnaghat Porespectively f) Ghorasal 132/33 breaker.	Additional Info Description eneration shortage ation, Sikalbaha E shut down. m unit -2 was shu PP GT-1 tripped ower Ltd. GT-2 a 3 KV 1T transfor	e in the evening peak how as the evening peak how at 23:15 due to the evening at 23:45 due to the evening at 02:45 (09/12/08) due not steam units were so	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) 8 Ilines, Interruption / Forced Load sharipur SBU GT-2 and Shahjibazar -2, 4 steam pipe line leakage. e to bypass damper problem. heduled shut down at 07:43 (09/12/08) on from 09:14 to 09:30 due to gas filling	ed etc. Forced load So no load shi	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
a) There was no ge b) Due to gas limita 5 & 6 are under c) Ashuganj Stean d) Fenchuganj CC e) Meghnaghat Porespectively f) Ghorasal 132/33 breaker.	Additional Info Description eneration shortage ation, Sikalbaha E shut down. m unit -2 was shu PP GT-1 tripped ower Ltd. GT-2 a 3 KV 1T transfor	e in the evening peak how as the evening peak how at 23:15 due to the evening at 23:45 due to the evening at 02:45 (09/12/08) due not steam units were so	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) lines, Interruption / Forced Load sharipur SBU GT-2 and Shahjibazar -2, 4 steam pipe line leakage. e to bypass damper problem. heduled shut down at 07:43 (09/12/08)	ed etc. Forced load So no load shi	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
a) There was no ge b) Due to gas limita 5 & 6 are under c) Ashuganj Stean d) Fenchuganj CC e) Meghnaghat Porespectively f) Ghorasal 132/33 breaker.	Additional Info Description eneration shortage ation, Sikalbaha E shut down. m unit -2 was shu PP GT-1 tripped ower Ltd. GT-2 a 3 KV 1T transfor	e in the evening peak how as the evening peak how at 23:15 due to the evening at 23:45 due to the evening at 02:45 (09/12/08) due not steam units were so	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) 8 Ilines, Interruption / Forced Load sharipur SBU GT-2 and Shahjibazar -2, 4 steam pipe line leakage. e to bypass damper problem. heduled shut down at 07:43 (09/12/08) on from 09:14 to 09:30 due to gas filling	ed etc. Forced load So no load shi	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
a) There was no ge b) Due to gas limita 5 & 6 are under c) Ashuganj Stean d) Fenchuganj CC e) Meghnaghat Porespectively f) Ghorasal 132/33 breaker.	Additional Info Description eneration shortage ation, Sikalbaha E shut down. m unit -2 was shu PP GT-1 tripped ower Ltd. GT-2 a 3 KV 1T transfor	e in the evening peak how as the evening peak how at 23:15 due to the evening at 23:45 due to the evening at 02:45 (09/12/08) due not steam units were so	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) 8 Ilines, Interruption / Forced Load sharipur SBU GT-2 and Shahjibazar -2, 4 steam pipe line leakage. e to bypass damper problem. heduled shut down at 07:43 (09/12/08) on from 09:14 to 09:30 due to gas filling	ed etc. Forced load So no load shi	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
a) There was no ge b) Due to gas limita 5 & 6 are under c) Ashuganj Stean d) Fenchuganj CC e) Meghnaghat Porespectively f) Ghorasal 132/33 breaker.	Additional Info Description eneration shortage ation, Sikalbaha E shut down. m unit -2 was shu PP GT-1 tripped ower Ltd. GT-2 a 3 KV 1T transfor	e in the evening peak how as the evening peak how at 23:15 due to the evening at 23:45 due to the evening at 02:45 (09/12/08) due not steam units were so	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) 8 Ilines, Interruption / Forced Load sharipur SBU GT-2 and Shahjibazar -2, 4 steam pipe line leakage. e to bypass damper problem. heduled shut down at 07:43 (09/12/08) on from 09:14 to 09:30 due to gas filling	ed etc. Forced load So no load shi	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
a) There was no ge b) Due to gas limita 5 & 6 are under c) Ashuganj Stean d) Fenchuganj CC e) Meghnaghat Porespectively f) Ghorasal 132/33 breaker.	Additional Info Description eneration shortage ation, Sikalbaha E shut down. m unit -2 was shu PP GT-1 tripped ower Ltd. GT-2 a 3 KV 1T transfor	e in the evening peak how as the evening peak how at 23:15 due to the evening at 23:45 due to the evening at 02:45 (09/12/08) due not steam units were so	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) 8 Ilines, Interruption / Forced Load sharipur SBU GT-2 and Shahjibazar -2, 4 steam pipe line leakage. e to bypass damper problem. heduled shut down at 07:43 (09/12/08) on from 09:14 to 09:30 due to gas filling	ed etc. Forced load So no load shi	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
a) There was no ge b) Due to gas limita 5 & 6 are under c) Ashuganj Stean d) Fenchuganj CC e) Meghnaghat Porespectively f) Ghorasal 132/33 breaker.	Additional Info Description eneration shortage ation, Sikalbaha E shut down. m unit -2 was shu PP GT-1 tripped ower Ltd. GT-2 a 3 KV 1T transfor	e in the evening peak how as the evening peak how at 23:15 due to the evening at 23:45 due to the evening at 02:45 (09/12/08) due not steam units were so	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) 8 Ilines, Interruption / Forced Load sharipur SBU GT-2 and Shahjibazar -2, 4 steam pipe line leakage. e to bypass damper problem. heduled shut down at 07:43 (09/12/08) on from 09:14 to 09:30 due to gas filling	ed etc. Forced load So no load shi	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
a) There was no ge b) Due to gas limita 5 & 6 are under c) Ashuganj Stean d) Fenchuganj CC e) Meghnaghat Porespectively f) Ghorasal 132/33 breaker.	Additional Info Description eneration shortage ation, Sikalbaha E shut down. m unit -2 was shu PP GT-1 tripped ower Ltd. GT-2 a 3 KV 1T transfor	e in the evening peak how as the evening peak how at 23:15 due to the evening at 23:45 due to the evening at 02:45 (09/12/08) due not steam units were so	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) 8 Ilines, Interruption / Forced Load sharipur SBU GT-2 and Shahjibazar -2, 4 steam pipe line leakage. e to bypass damper problem. heduled shut down at 07:43 (09/12/08) on from 09:14 to 09:30 due to gas filling	ed etc. Forced load So no load shi	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
a) There was no ge b) Due to gas limita 5 & 6 are under c) Ashuganj Stean d) Fenchuganj CC e) Meghnaghat Porespectively f) Ghorasal 132/33 breaker.	Additional Info Description eneration shortage ation, Sikalbaha E shut down. m unit -2 was shu PP GT-1 tripped ower Ltd. GT-2 a 3 KV 1T transfor	e in the evening peak how as the evening peak how at 23:15 due to the evening at 23:45 due to the evening at 02:45 (09/12/08) due not steam units were so	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) 8 Ilines, Interruption / Forced Load sharipur SBU GT-2 and Shahjibazar -2, 4 steam pipe line leakage. e to bypass damper problem. heduled shut down at 07:43 (09/12/08) on from 09:14 to 09:30 due to gas filling	ed etc. Forced load So no load shi	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
a) There was no ge b) Due to gas limita 5 & 6 are under c) Ashuganj Stean d) Fenchuganj CC e) Meghnaghat Porespectively f) Ghorasal 132/33 breaker.	Additional Info Description eneration shortage ation, Sikalbaha E shut down. m unit -2 was shu PP GT-1 tripped ower Ltd. GT-2 a 3 KV 1T transfor	e in the evening peak how as the evening peak how at 23:15 due to the evening at 23:45 due to the evening at 02:45 (09/12/08) due not steam units were so	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) 8 Ilines, Interruption / Forced Load sharipur SBU GT-2 and Shahjibazar -2, 4 steam pipe line leakage. e to bypass damper problem. heduled shut down at 07:43 (09/12/08) on from 09:14 to 09:30 due to gas filling	ed etc. Forced load So no load shi	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
a) There was no ge b) Due to gas limita 5 & 6 are under c) Ashuganj Stean d) Fenchuganj CC e) Meghnaghat Porespectively f) Ghorasal 132/33 breaker.	Additional Info Description eneration shortage ation, Sikalbaha E shut down. m unit -2 was shu PP GT-1 tripped ower Ltd. GT-2 a 3 KV 1T transfor	e in the evening peak how as the evening peak how at 23:15 due to the evening at 23:45 due to the evening at 02:45 (09/12/08) due not steam units were so	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) 8 Ilines, Interruption / Forced Load sharipur SBU GT-2 and Shahjibazar -2, 4 steam pipe line leakage. e to bypass damper problem. heduled shut down at 07:43 (09/12/08) on from 09:14 to 09:30 due to gas filling	ed etc. Forced load So no load shi	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	ted Areas		
a) There was no ge b) Due to gas limits 5 & 6 are under c) Ashuganj Stean d) Fenchuganj CC e) Meghnaghat Porespectively f) Ghorasal 132/33 breaker. g) Gopalganj 132/	Additional Info Description peneration shortage ation, Sikalbaha E shut down. In unit -2 was shu IPP GT-1 tripped ower Ltd. GT-2 a 3 KV 1T transfor	e in the evening peak how as the evening peak how at 23:15 due to the evening at 23:45 due to the evening at 02:45 (09/12/08) due not steam units were so	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) 8 Ilines, Interruption / Forced Load sharipur SBU GT-2 and Shahjibazar -2, 4 steam pipe line leakage. e to bypass damper problem. heduled shut down at 07:43 (09/12/08) on from 09:14 to 09:30 due to gas filling	ed etc. Forced load So no load shi	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)			
a) There was no ge b) Due to gas limita 5 & 6 are under c) Ashuganj Stean d) Fenchuganj CC e) Meghnaghat Porespectively f) Ghorasal 132/33 breaker.	Additional Info Description peneration shortage ation, Sikalbaha E shut down. In unit -2 was shu IPP GT-1 tripped ower Ltd. GT-2 a 3 KV 1T transfor	e in the evening peak how as the evening peak how at 23:15 due to the evening at 23:45 due to the evening at 02:45 (09/12/08) due not steam units were so	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) 8 Ilines, Interruption / Forced Load sharipur SBU GT-2 and Shahjibazar -2, 4 steam pipe line leakage. e to bypass damper problem. heduled shut down at 07:43 (09/12/08) on from 09:14 to 09:30 due to gas filling	ed etc. Forced load So no load shi	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)		General Manager	
a) There was no ge b) Due to gas limits 5 & 6 are under c) Ashuganj Stean d) Fenchuganj CC e) Meghnaghat Porespectively f) Ghorasal 132/33 breaker. g) Gopalganj 132/	Additional Info Description Ineration shortage ation, Sikalbaha E shut down. In unit -2 was shu IPP GT-1 tripped Ower Ltd. GT-2 a 3 KV T2 transfor (33 KV T2 transfor	e in the evening peak how as the evening peak how at 23:15 due to the evening at 23:45 due to the evening at 02:45 (09/12/08) due not steam units were so	2) Raozan -1 (19/11/08) 3) Shajibazar-2 (13/07/08) 4) Shajibazar-4 (18/10/08) 5) Ghorasal-1 (30/09/08) 6) Meghnaghat GT-1 (31/10/08) 7) Haripur SBU GT-2 (25/11/08) 8) Shajibazar-5 (22/11/08) 8 Ilines, Interruption / Forced Load sharipur SBU GT-2 and Shahjibazar -2, 4 steam pipe line leakage. e to bypass damper problem. heduled shut down at 07:43 (09/12/08) on from 09:14 to 09:30 due to gas filling	ed etc. Forced load So no load shi	rge (19/06/08) iteam (21/11/08) · GT-6(04/12/0)	Deputy (General Manager	