POWER GRID COMPANY OF BANGLADESH LTD. NATIONAL LOAD DESPATCH CENTER QF-L DAILY REPORT P													
										orting Date :	11-Oct-20	0	
Till now the maximum genera	tion is : -	10-Oct-20	12893 MW				21	:00 Hrs o					
The Summary of Yesterday's Day Peak Generation :			646.0 MW	n & Demand	Hour :	12:00		Today's Actual Min. Gen. at		3:00		51 MW	
Evening Peak Generation :			2650.0 MW		Hour :	12:00		Available Max G		:		04 MW	
E.P. Demand (at gen end) :			2650.0 MW		Hour :	19:30		Max Demand (E				00 MW	
Maximum Generation :			2650.0 MW		Hour :	19:30		Reserve(Genera				04 MW	
Total Gen. (MKWH) :			255.2	System	Load Factor	: 84.04%	6	Load Shed	:			0 MW	
, <i>i</i>				THROUGH EAST-W									
Export from East grid to West grid						-179 MW	at	19:00		Energy		MKWHR.	
Import from West grid to East grid				-		MW	at	-		Energy		- MKWHR.	
Water Level of Kaptai Lake			11-Oct-20										
Actual :	101.99	Ft.(MSL),			Rule c	urve :	106.90	Ft.(MSL)					
Gas Consumed :	Total =		84.99 MMCFD.			Oil Com	nsumed (PDB) :						
Gas Consumed .	Total =		104.55 WINCI D.			Oil Coil	isumeu (FDD).		HSD :			Liter	
									FO :			Liter	
Cost of the Consumed Fuel (PDB-	+Pvt) :	Ga	as :	Tk163,746,421									
:		Co	oal :	Tk80,695,582			Oil	: Tk566,296,257		Total : Th	k810,738,261		
		Load Shedding 8	Other Informatio	n									
A	Maatandau							Taday					
Area	Yesterday			Estimated Demand (S/S and)			Today Estimated Shede	ding (S/S and)		Rates of Shedding		
	MW			MW	S/S enu)			Louinateu oneu	MW		On Estimated Dem		
Dhaka	0	0:00		4605					10100	0	0%	anu)	
Chittagong Area	õ	0:00		1571						0	0%		
Khulna Area	0	0:00		1408						0	0%		
Rajshahi Area	0	0:00		1273						0	0%		
Cumilla Area	0	0:00		1150						0	0%		
Mymensingh Area	0	0:00		928						0	0%		
Sylhet Area	0	0:00		513						0	0%		
Barisal Area	0	0:00		239						0	0%		
Rangpur Area Total	0	0:00		716 12401						0	0%		
Total	U			12401						U			
Ir	formation of the	Generating Units u	under shut down.										
Planne	ed Shut- Down					Forced	Shut- Down						
1) Barapukuria ST: Unit-1,2													
2) Baghabari-71 MW,100								0 MW					
							rasal Unit-1,2,3,4						
							uganj unit-3,4						
						 5) Kapt 6) Raoz 							
							lirganj-335 MW						
						/) 0100	inganj 555 miri						
Additio	onal Information	of Machines, line	es, Interruption / F	Forced Load shed etc	•								
		Description						Comments on F	Jouror Interrupt	lion			
a) Bibiyana-Kaliakoir 400 kV Ckt-1			wing Dist 71 R-ph	ase relay and				Comments on r	ower interrupt				
was switched on at 12:06.	hipped at 05.57	nom both cha she	wing bist. 21 it pi	lase relay and									
b) HVDC Bheramara filter 10 CF	16 at 400 kV Bus	was shut down at	08:38.										
c) Saidpur 132/33 kV T1 transformer was under shut down from 08:20 to 16:45 for A/M.													
d) Panchagar 132/33 kV T3 transformer was under shut down from 08:20 to 17:25 for D/W.									About 20 MW power interruption occurred under Panchagar S/S area				
									from 08:20 to 17:25.				
e) Bheramara 410 MW CCPP was			oply line problem.										
f) Bheramara 230 kV shunt reacto													
g) Magura- Norail 132 kV Ckt-1 w													
 h) Hathazari-Baroirhat 132 kV Ckt auitabad an at 11/36 	-1 tripped at 11:2	to from both end st	nowing Dist. Y,B-pr	hase relays and was									
switched on at 11:36.	sformer tripped a	t 16:57 due to 33 l	() feeder fault and	was				About 50 MW or	wer interruption	occurred und	er lessore S/S ar	69	
 i) Jessore 132/33 kV T1 & T2 transformer tripped at 16:57 due to 33 kV feeder fault and was switched on at 17:26. 									About 50 MW power interruption occurred under Jessore S/S area from 16:57 to 17:26.				
switcheo on at 17.20. j) Baghaban 71 MW was synchronized at 16:05.									.20.				
k) Khulna 225 MW STG was shut		nd was synchronize	ed at 18:24.										
I) Shahzibazar 330 MW GT-2 tripp	ed at 14:43 and	was synchronized	at 16:08.										
m) Bheramara 230/132 kV GT-2 transformer tripped at 19:48 showing differentia; relay at 132 kV end								About 50 MW po from 19:48 to 20		n occurred unde	er Khulna Zone		
and was switched on at 20:59.									:59.				
n) Chandpur 150 MW GT tripped at 19:53													
 a) Tangail-RPCL 132 kV Ckt-2 was shut down at 20:09 due to overload to other Ckt. b) Bhulta 132/33 kV T2 transformer was shut down from 21:10 to 21:53 due to red hot maintenance 									wor interrent'	occurred us d	or Rhulto S/S area		
p) phulia 122/36 kV 12 transformer was shut down from 21:10 to 21:53 due to red not maintenance at 132 kV R-phase CB.									About 20 MW power interruption occurred under Bhulta S/S area from 21:10 to 21:53.				
at 132 KV R-phase CB. q) Patuakhali 132/33 KV T1 transformer was shut down at 07:L03(11/10/2020) for A/M.													
r) Meghnaghat-Aminbazar 230 kV													
s) Kallyanpur 132/33 kV T2 transfe			,										
t) Shahjibazar 132/33 kV T2 transformer tripped at 22:08 showing lockout relay at 33 kV end and was								About 20 MW po	About 20 MW power interruption occurred under Shahjibazar S/S area				
switched on at 22:23.								from 22:08 to 22	:23.				
Sub Divisional Engineer			Evecuti	ve Engineer					Q.10	perintendent E	ngineer		
Network Operation Division				peration Division						ad Despatch (