| POWER GRID COMPANY OF BANGLADESH LTD. NATIONAL LOAD DESPATCH CENTER DALLY REPORT | | | | | | | | | | | |
|--|------------------------------|---|-------------------------------------|---|---|---|--------------------------------|-----------------|---------------|-------------------------------------|-----------|
| | | | | | | | | | orting Date : | 29-May-23 | |
| Till now the maximum g The Summary of Yesterd | eneration is : - | 28-May- | 23 Generation & Dema | nd | | 21:0 | D Hrs on Today's Actual Min | 19-Apr-23 | ion & Doma | nd | |
| Day Peak Generation : | iay s | 20-may- | 11786.0 MW | Hour : | 12:00 | | Min. Gen. at | 6:00 |) | 110 | 10960 |
| Evening Peak Generation : | | | 14136.0 MW | Hour : | 21:00 | | Available Max Generation | ation : | | | 14894 |
| E.P. Demand (at gen end) : | | | 14218.0 MW | Hour : | 21:00 | | Max Demand (Evenir | ig): | | | 14500 |
| Maximum Generation : | | | 14136.0 MW | Hour : | 21:00 | | Reserve(Generation | end) | | | 394 |
| Total Gen. (MKWH) : | | | 282.9 | System Load Factor | : 83.40% | | Load Shed | : | | | 0 |
| Export from East grid to Wes | ROUGH EAST-WEST INTERCONNECT | OR 0 MW MW | at | 22:00 | | Energy | | | | | |
| Import from West grid to Eas | st grid :- Maximum Water | Level of Kaptai Lake at 6:00 A M on 72.95 Ft.(MSL). | - 29-May-23 | | | at | - Ft.(MSL) | | Energy | | |
| Gas Consumed - | | 72.95 FL(MSL), | 1194.32 MMCFD. | Rule curve | | 76.60 isumed (PDI | | | | | |
| Gas Consumed . | | i olar – | 1194.32 MMCPD. | | Oli Coli | ISUMBO (PDI | | HSD : FO : | | | |
| Cost of the Consumed Fuel (PDB+Pvt) : : | | | Gas : Coal : | Tk177,519,719 Tk126,384,959 | | Oil | : Tk689,938,998 | | Total : | Tk993,843,675 | |
| | | Load Shedding & C | ther Information | | | | | | | | |
| Area | | Yesterday | Es | stimated Demand (S/S end) MW | | | Today Estimated Shedding | (S/S end) MW | | Rates of Shedding | |
| Dhaka | | 18 0:00 | | 4858 | | | | MW | | (On Estimated Demand) 0% | |
| Chittagong Area | | 0 0:00 | | 4858 | | | | 0 | | 0% | |
| Khulna Area | | 0:00 | | 1873 | | | | 0 | | 0% | |
| Rajshahi Area | | 25 0:00 | | 1628 | | | | 0 | | 0% | |
| Cumilla Area | | 10 0:00 | | 1339 | | | | 0 | | 0% | |
| Mymensingh Area Svlhet Area | | 25 0:00 0 0:00 | | 996 558 | | | | 0 | | 0% 0% | |
| Sylnet Area Barisal Area | | 0 0:00 | | 466 | | | | 0 | | 0% | |
| Rangpur Area | | 0 0:00 | | 910 | | | | 0 | | 0% | |
| Total | | 78 | | 13965 | | | | 0 | | | |
| | | Information of the Generating Units under shut do | vn. | | | | | | | | |
| Planned Shut- Down 1) Barapukuria ST: Uni- 2 | | | | | | | | | | | |
| | | | | | 2) Ghor 3) Bhul 4) Bagh 5) Raoz 6) Sidd | rasal-3,7 a Nuton Bidd nabari-71,100 zan unit-2 hirganj 210 M ibazar 330 M | ut) MW | | | | |
| Outage | Restore | Additional Information of Machines, | ines, Interruption / Forced Load si | hed etc. | | | | | | | Remark |
| Time | Time | | | | | | | | | | |
| 8:01 8:05 | - | Juldah 132/33kV S/S 132/33 KV 406T T-1 LT Project V | | | | | | | | | |
| 8:05 | - | Juldah 132/33kV S/S 132/33 KV 406T T-1 HT Project V | Vork S/D Due to New 50/75 MVA tran | nsformer replacement. | | | | | I | | |
| 9:26 | 10:03 | Khulna 330MW P/8 GT Synchronized. 7 Tangai 132/3X/VS 157 - L1 Tripped showing ABB REF615 relays Due to 33kV Korotiya Feeder fault. 33 | | | | | | | | 32.0MW load interrup. | |
| 9:26 | 10:02 | Tangai 132/3AV VS 11-12 L Tripped sitowing ABB REFOIS telays Due to 33AV Kototya Feeder fault. | | | | | | | | 32.0MW load interrup. | |
| 9:26 | 10:00 | Tangail 132/33kV S/S Tr-1 HT Tripped showing Alstom MCGG and Control Panel relays Due to 33kV Korotiya Feeder fault. | | | | | | | | 32.0MW load interrup. | |
| 9:31 | 10:48 | Rampur 230/132/33 S/S 132kV BUS-02 Forced S/D Du | e to gas filling at 263GC1. | | | | | | | | |
| 9:51 | | Khulna 330MW P/S STG Synchronized. | | | | | | | I | | |
| 10:21 | 10:48 | Maniknagar-Narinda 132kV Ckt-2 Tripped from Manikn | agar 132/33kV end showing 1) Trip. | Main protection trip. relays. | | | | | I | | |
| 10:22 | 11:50 | Narinda 132/33 kV GT2 tripped due to trial of 33kV Bon | | | | | 10MW load interrup. | | | | |
| 10:54 | 10:58 | Saidpur 132/33kV S/S TR-2 (404T) LT Tripped showing | | | ŀ | 48.0MW load interrup. | | | | | |
| 10:54 11:24 | 11:00 12:36 | Saidpur 132/33kV SIS TR-3 (424T) LT Tripped showing EIF., O/C relays Due to 33kv EPZ Feeder Fault. 48.0MW load interrup. | | | | | | | | | |
| 11.24 | 11:32 | Goglagni 132/33W SIS Gallamari-1 Scheduled SID Due to Testing. | | | | | | | | | |
| 11:32 | 11.32 | Rampal 400/2304/SIS/CT-1LT is restored. Rampal 400/2304/SIS/CT-1LT is restored. | | | | | | | | | |
| 11:32 | 13:45 | Nampai 400/230/V KL-1 - 1 Carigeo. Jamaipur-Mymensingh 132V (Ck-1 Scheduled S/D from Mymensingh 132/33KV end Due to LA connection and from Jamaipur 132/33KV | | | | | | | | | |
| | | antappu-mymensingin 152x7 CM-1 Scheduled Sch nom mymensingin 152/55x7 end Dae to Ex connection and non samapur 152/55x7 | | | | | | | | | |
| 12:10 | 13:00 | Barapukuria S/S-P/S 230 kV Ckt-1 Tripped from Barapu | kuria 230kV end showing distance r | elays Due to thundering. | | | | | | | |
| 12:30 | 12:54 | Hathazari-Kaptai 132kV Ckt-1 Scheduled S/D from Kap | tai 132/33kV end Due to monthly ma | intenance. | | | | | | 60.0MW load interrup. Kaptai 132 | /33kV end |
| 12:47 | 12:50 | Shikalbaha 132/33kV S/S TR LT Forced S/D Due to due | | | | | | | | | |
| 12:48 | 13:13 | Gopalganj 132/33kV S/S Gallamari-2 Scheduled S/D D | ue to Testing. | | | | | | I | | |
| 12:50 13:00 | 12:57 13:03 | Hathazari-Kaptai 132kV Ckt-2 Scheduled S/D from Kap | tai 132/33kV end Due to Maintenanc | e purpose. | | | | | | 25.0MW load interrup. Kaptai 132/33 | 3kV end |
| 13:00 | 13:03 | Hathazari-Kaptai 132kV Ckt-1 Scheduled S/D from Kap Saidpur 132/33kV S/S TR-2 (404T) LT Forced S/D Due | tai 132/33kV end Due to Test purpos | ie. | | | | | I | | |
| 13:12 | 15:05 | Saidpur 132/33kV S/S TR-2 (4041) LT Forced S/D Due Saidpur 132/33kV S/S TR-2 (4041) HT Forced S/D Due | | | | | | | | | |
| 14:06 | 10.04 | Sirajgonj 210MW Unit-1 GT was sync. | 101 ST SORV ET 2 I BOUGI HOIR. | | | | | | | | |
| 14:20 | 14:48 | Bagerhat-Bhandaria 132 kV Ckt-1 Scheduled S/D from | Bagerhat 132/33kV end Due to Tree | Trimming | | | | | | | |
| 15:23 | - | Sirajgonj Gas 225MW Unit-2 was shutdown due to gas shortage. | | | | | | | | | |
| 17:15 | - | Sirajgonj 210MW Unit-1 ST was sync. | | | | | | | | | |
| - | 17:48 | Kalurghat 132/33kV S/S TRFO-01(506T) LT is restored | | | | | | | | | |
| 21:09 | | Khulna 330 MW CCPP was shutdown. | | | | | | | | | |
| 21:09 | - | Khulna 330 MW P/S Di-Synchronize . | | | | | | | | | |
| 2:27 | - | Adani Power Jharkhand Ltd. unit-2 was sync. | | | | | | | | | |
| 3:02 4:09 | - | Adani Power Jharkhand Ltd. unit-2 tripped due to turbin | e protection. | | | | | | | | |
| 4:09 | | Adani Power Jharkhand Ltd. unit-2 was sync. Maniknagar-Siddhirganj 230kV Ckt-1 Scheduled S/D fr | Manikagan 220/122k/ and Dura | to EPS 02 Tower Work | | | | | 1 | | |
| 0.41 | - | manimagar-oluuningenj zouk v Ukt-i ocheduled S/D m | an manistragar 200/102kv end Due | IO ENG-02 TOWER WORK. | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |

Sub Divisional Engineer Network Operation Division

Executive Engineer Network Operation Division Superintendent Engineer Load Despatch Circle